


Rich Mill RMH8

- · Screw on clamping system
 - → Adopt and stable clamping system
- · Reinforce rigidity and enhance clamping power
 - ightarrow Appling shim system, prevent cutter damage when insert breaks
- · Adopting exchangeable shim
 - →Using various kinds of cutter (Approach angle 45, 75, 80)
 - → Stable clamping power with insert



(Approach angle 88°)